This Page Is Inserted by IFW Operations and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.




Figure 1 ...




Figure 2




Figure 3




Figure 4




Figure S




Figure 6




Figure 7

		_	<u>!</u>
	CUSTOMER: LASER PROGRAM: CAD FILE: REV REVISION B FRONTLINE BASKET ANGLE FRAME 12 BASKET ANGLE FRAME 12	TY' DATE	
	48		
	9.250		
	BREAK UP 90°	1.380	:
	LASER OR SHEAR		; ;
			•
	. (2 PC'S REQ.D)		
,	FRONTLINE INTERNATIONAL INC. BASKET ANGLE FRAME 12	7/15/03 C N/A N/A 10F1 A	
	BEREET, AGUALDE ACOUSTY AND AVENUES AND AVENUES AND AVENUES OF		

Figure 8

.




Figure 9




Figure 10




Figure 11




Figure 12





Figure 13



Frame 14